QUALITY CONTROL

BR No: 220/31.07.2013.

Name of the Work: Providing UGD connection to SC/ST houses at papamma compound at kammagondanahalli in Shettyhalli Sub-Division Ward no-12.

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed 2 years back.

Assistance Executive Engineer
Shetty Halli Sub Division
Bruhat Bengaluru Mahanagara Palike

Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike